

Tracing a gas leak on a Large Cylinder Pack

Check for leaks using the following procedure:

- while the gas cylinder is still turned on, close the ring main shut off valve (turn to the 90° position).
- if you have a postmix system operating from this manifold, close the gas supply valve on (or adjacent) to the postmix machine
- turn all gas cylinders off
- wait for a short time: has the needle dropped on the pressure gauge on the BOC regulator?
- If it has, telephone BOC Sureflow
- If it has not, carry on to the next step
- keep all cylinders turned off and return both ring main shut off valves to the open position (the in-line position)
- if the needle falls back towards zero, the gas leak is on the brewery or postmix equipment - call your brewery or soft drinks services engineers for help.